

Discontinuation – End of Life (EOL)

27.11.2024

Yellow chromated D-Sub connectors

Dear customer,

The following products of our product range will be discontinued.

A list of the affected products is attached at the end of this letter.

In case of questions or requirements do not hesitate to contact the known contact person.

Please forward this important information also to other responsible departments in your company.

Thank you very much for your patronage for our products. We are looking forward to continue working with you.

With best regards

CONEC Elektronische Bauelemente GmbH

Yellow chromated D-Sub connectors

| | | | |
|-----------------|-------------|-----------------|-----------------|
| 16-510453 | 161A10029XN | 161C10019X | 5013W6SXX99A10X |
| 164A03509A | 161A10019X | 5003W3PXX73K20X | 162A12219X |
| 161A10039X | 162A10039X | 162A10139X | 161A10039XE |
| 161C17779X | 161A10089X | 161C10089X | 162A10169X |
| 5005W5SXX99A10X | 162A10029X | 162C10039XE | 5017W5SBR49A10X |
| 13-506724 | 162A10069X | 162C10069XE | 164A03509AE |
| 5005W5PXX99A10X | 162C10069X | 5013W6PXX99A10X | 163X06170A |
| 163X06140A | 161A10020X | 161A10069XN | 161A10129XN |
| 163X06160A | 161A10029X | 161A10079X | 161A10139X |
| 13-506081 | 161A10029XE | 161A10080X | 161A10149X |
| 161A00639A | 161A10049X | 161A10089XN | 161A10159X |
| 161A01049A | 161A10049XE | 161A10099X | 161A10159XN |
| 161A04859A | 161A10059X | 161A10109X | 161A10169X |
| 161A10010X | 161A10059XE | 161A10119X | 161A10179X |
| 161A10019XE | 161A10069X | 161A10129X | 161A10179XN |
| 161A10179XNE | 161B10149X | 162A10019X | 162A10179XN |
| 161A10189X | 161B10169X | 162A10019XE | 162A10189X |
| 161A10189XN | 161B10189X | 162A10029XE | 162A10189XE |
| 161A10199X | 161B10199X | 162A10030X | 162A10189XN |
| 161A10199XN | 161B10679X | 162A10039XE | 162A10199X |
| 161A10209X | 161B16779X | 162A10039XN | 162A10209X |
| 161A10209XN | 161C10019XE | 162A10049X | 162A10209XN |
| 161A10709X | 161C10029X | 162A10049XE | 162A10660X |
| 161A12029X | 161C10029XE | 162A10059X | 162A10669X |
| 161A14069X | 161C10039X | 162A10059XE | 162A10689X |
| 161A14259X | 161C10039XE | 162A10059XN | 162A10699X |
| 161A17379X | 161C10049X | 162A10069XE | 162A10709X |
| 161A17389X | 161C10049XE | 162A10069XN | 162A12909X |
| 161A17409X | 161C10059X | 162A10079X | 162A13069X |
| 161A17509X | 161J10019X | 162A10079XN | 162A16599X |
| 161A17519X | 161J10029X | 162A10089X | 162A17189X |
| 161A17639X | 161J10039X | 162A10089XN | 162A17789X |
| 161A18219X | 161J10049X | 162A10099X | 162A17929X |
| 161B10019X | 161J10099X | 162A10109X | 162A19649X |
| 161B10029X | 161J10139X | 162A10109XE | 162B10019X |
| 161B10039X | 161X10019X | 162A10119X | 162B10029X |
| 161B10049X | 161X10029X | 162A10129X | 162B10039X |
| 161B10069X | 161X10039X | 162A10139XN | 162B10049X |
| 161B10079X | 161X10191A | 162A10139XNE | 162B10059X |
| 161B10089X | 162A00939A | 162A10149X | 162B10069X |

| | | | |
|-----------------|------------------|------------------|------------------|
| 161B10139X | 162A10010X | 162A10149XN | 162B10089X |
| 162B10149X | 162B10189X | 162A10169XE | 162B10119X |
| 162C01159A | 2HDD15SAM99B30Y | 5005W5SXX57H20X | 5017W2PXXK99A10X |
| 162C06330A | 2HDD15SCM99B30X | 5005W5SXX57H20XE | 5017W2PXXK99A30X |
| 162C10019X | 2HDD26SCR99B30C | 5007W2PXXK99A10X | 5017W2SCR76C40X |
| 162C10019XE | 2STD09PAM99A10X | 5008W8PJX78G10X | 5017W5PXXK99A10X |
| 162C10029X | 2STD09PCM99B30X | 5008W8PXX44A10X | 5017W5SXXK99A10X |
| 162C10029XE | 2STD09SAM99A10X | 5008W8PXX99A10X | 5024W7PCM99A10X |
| 162C10039X | 2STD09SAM99B30X | 5008W8PXX99N20X | 5024W7PCS98S90A |
| 162C10049X | 2STD15PAM99A10X | 5008W8SXX44A10X | 5024W7PCS98S90B |
| 162C10049XE | 2STD15SAM99A10X | 5008W8SXX99A10X | 5024W7SCM99A10X |
| 162C10059X | 2STD50SCM99B30X | 5008W8SXX99A10XE | 5024W7SCM99S90A |
| 162C10089X | 5003W3PXX48F20X | 5009W4PBR49A10X | 502W2CPXX56K40X |
| 162C10119X | 5003W3PXX58A10X | 5009W4PBR49A10XE | 502W2CPXX99A10X |
| 162C10149X-S | 5003W3PXX99A10X | 5013W3PCM42A10X | 502W2CPXX99A10XE |
| 162C12059X | 5003W3PXX99A30X | 5013W3SAM99A10X | 502W2CSXX51A50X |
| 162J10029X | 5003W3PXX99N20X | 5013W3SCM99A10X | 502W2CSXX99A10X |
| 162J10039X | 5003W3SXX52A10X | 5013W3SXXK99A10X | 521WA4PCM99A10X |
| 162J10049X | 5003W3SXX99A10X | 5013W6PAM99A10X | 521WA4PCT98S90B |
| 162J10119X | 5003W3SXX99S90A | 5013W6PCM99A10X | 521WA4PCU99A10X |
| 162J10179X | 5005W1PXXK99A10X | 5013W6PCR58A10X | 521WA4SAU58A10X |
| 162J10799X | 5005W1PXXK99A30X | 5013W6SAM99A10X | 521WA4SCR76E40X |
| 162J12129X | 5005W1SXXK99A10X | 5017W2PCM42A10X | 521WA4SCR99S90B |
| 162X11760X | 5005W5PXX58N10X | 5017W2PCM99A10X | DSSAXSMAB01X |
| 164A07330A | 5005W5SXX52A40X | 5017W2PCR76C20X | DSSAXSRCD01A |
| 2008W8SXXR4B30X | 2HDD15PCM99A10X | 162A10179X | DSSBXPMA01X |
| DSSDXSMCB01X | 16-511373 | 2005W5SXXR4B30X | |
| DSSEXSTCM39A | | | |