

Discontinuation – End of Life (EOL)

27.11.2024

Yellow chromated D-Sub connectors

Dear customer,

The following products of our product range will be discontinued.

A list of the affected products is attached at the end of this letter.

In case of questions or requirements do not hesitate to contact the known contact person.

Please forward this important information also to other responsible departments in your company.

Thank you very much for your patronage for our products. We are looking forward to continue working with you.

With best regards

CONEC Elektronische Bauelemente GmbH

Yellow chromated D-Sub connectors

16-510453	161A10029XN	161C10019X	5013W6SXX99A10X
164A03509A	161A10019X	5003W3PXX73K20X	162A12219X
161A10039X	162A10039X	162A10139X	161A10039XE
161C17779X	161A10089X	161C10089X	162A10169X
5005W5SXX99A10X	162A10029X	162C10039XE	5017W5SBR49A10X
DSSEXSTCM39A	162A10069X	162C10069XE	164A03509AE
5005W5PXX99A10X	162C10069X	5013W6PXX99A10X	163X06170A
163X06140A	161A10020X	161A10069XN	161A10129XN
163X06160A	161A10029X	161A10079X	161A10139X
13-506081	161A10029XE	161A10080X	161A10149X
161A00639A	161A10049X	161A10089XN	161A10159X
161A01049A	161A10049XE	161A10099X	161A10159XN
161A04859A	161A10059X	161A10109X	161A10169X
161A10010X	161A10059XE	161A10119X	161A10179X
161A10019XE	161A10069X	161A10129X	161A10179XN
161A10179XNE	161B10149X	162A10019X	162A10179XN
161A10189X	161B10169X	162A10019XE	162A10189X
161A10189XN	161B10189X	162A10029XE	162A10189XE
161A10199X	161B10199X	162A10030X	162A10189XN
161A10199XN	161B10679X	162A10039XE	162A10199X
161A10209X	161B16779X	162A10039XN	162A10209X
161A10209XN	161C10019XE	162A10049X	162A10209XN
161A10709X	161C10029X	162A10049XE	162A10660X
161A12029X	161C10029XE	162A10059X	162A10669X
161A14069X	161C10039X	162A10059XE	162A10689X
161A14259X	161C10039XE	162A10059XN	162A10699X
161A17379X	161C10049X	162A10069XE	162A10709X
161A17389X	161C10049XE	162A10069XN	162A12909X
161A17409X	161C10059X	162A10079X	162A13069X
161A17509X	161J10019X	162A10079XN	162A16599X
161A17519X	161J10029X	162A10089X	162A17189X
161A17639X	161J10039X	162A10089XN	162A17789X
161A18219X	161J10049X	162A10099X	162A17929X
161B10019X	161J10099X	162A10109X	162A19649X
161B10029X	161J10139X	162A10109XE	162B10019X
161B10039X	161X10019X	162A10119X	162B10029X
161B10049X	161X10029X	162A10129X	162B10039X
161B10069X	161X10039X	162A10139XN	162B10049X
161B10079X	161X10191A	162A10139XNE	162B10059X
161B10089X	162A00939A	162A10149X	162B10069X

161B10139X	162A10010X	162A10149XN	162B10089X
162B10149X	162B10189X	162A10169XE	162B10119X
162C01159A	2HDD15SAM99B30Y	5005W5SXX57H20X	5017W2PXXK99A10X
162C06330A	2HDD15SCM99B30X	5005W5SXX57H20XE	5017W2PXXK99A30X
162C10019X	2HDD26SCR99B30C	5007W2PXXK99A10X	5017W2SCR76C40X
162C10019XE	2STD09PAM99A10X	5008W8PJX78G10X	5017W5PXXK99A10X
162C10029X	2STD09PCM99B30X	5008W8PXX44A10X	5017W5SXXK99A10X
162C10029XE	2STD09SAM99A10X	5008W8PXX99A10X	5024W7PCM99A10X
162C10039X	2STD09SAM99B30X	5008W8PXX99N20X	5024W7PCS98S90A
162C10049X	2STD15PAM99A10X	5008W8SXX44A10X	5024W7PCS98S90B
162C10049XE	2STD15SAM99A10X	5008W8SXX99A10X	5024W7SCM99A10X
162C10059X	2STD50SCM99B30X	5008W8SXX99A10XE	5024W7SCM99S90A
162C10089X	5003W3PXX48F20X	5009W4PBR49A10X	502W2CPXX56K40X
162C10119X	5003W3PXX58A10X	5009W4PBR49A10XE	502W2CPXX99A10X
162C10149X-S	5003W3PXX99A10X	5013W3PCM42A10X	502W2CPXX99A10XE
162C12059X	5003W3PXX99A30X	5013W3SAM99A10X	502W2CSXX51A50X
162J10029X	5003W3PXX99N20X	5013W3SCM99A10X	502W2CSXX99A10X
162J10039X	5003W3SXX52A10X	5013W3SXX99A10X	521WA4PCM99A10X
162J10049X	5003W3SXX99A10X	5013W6PAM99A10X	521WA4PCT98S90B
162J10119X	5003W3SXX99S90A	5013W6PCM99A10X	521WA4PCU99A10X
162J10179X	5005W1PXXK99A10X	5013W6PCR58A10X	521WA4SAU58A10X
162J10799X	5005W1PXXK99A30X	5013W6SAM99A10X	521WA4SCR76E40X
162J12129X	5005W1SXXK99A10X	5017W2PCM42A10X	521WA4SCR99S90B
162X11760X	5005W5PXX58N10X	5017W2PCM99A10X	DSSAXSMAB01X
164A07330A	5005W5SXX52A40X	5017W2PCR76C20X	DSSAXSRCD01A
2008W8SXXR4B30X	2HDD15PCM99A10X	162A10179X	DSSBXPMA01X
DSSDXSMCB01X	16-511373	2005W5SXXR4B30X	